COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MT23ERO

Ford Ranger WILDTRAK 2.0 ECOBLUE 213PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44067
Cap Code	FORA20WILD7DTA4 6 L

Details

Location	Bedford	**Colour**	SILVER	**CAP Below**	£10,550.00
Reg. date	25/04/2023	**VIN**	6FPPXXMJ2PNB67422	**Gearbox**	AUTOMATIC
Year	2023	**Body Style**	Pickup Double Cab	**Gears**	1
Mileage	83,658 Miles Not Warranted	**MOT Due**	24/04/2027	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£13,250.00		
GVW	3270kg	**CAP Average**	£12,300.00		

WARNING LIGHT ON DASH AD BLUE, E/MIRRORS, TOW BAR, ALLOY WHEELS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	


Features



- Front parking sensor
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Rear parking sensor

Photos














FORD
e5*2007/46*0080
6FPPXXMJ2PNB67422
3270 KG
6260 KG
1480 KG
1910 KG
VIN
2AB
0.50
MADE IN SOUTH AFRICA







P R N D S
Front camera malfunction Service required






Condition Check




Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Wheel nsf
Scratched
Up To 50mm



3: Wheel nsr
Scratched
Up To 50mm



4: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK