COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FP75OKE

Ford Transit Custom 280 2.0 ECOBLUE 136PS LIMITED

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	57322
Cap Code	FOTU208SL6VDTM2 2 L

Details

Location	Bedford	**GVW**	2825kg	**CAP Clean**	£22,250.00
Reg. date	31/10/2025	**Colour**	WHITE	**CAP Average**	£21,350.00
Year	2025	**VIN**	WF0RXXTA4RSG45199	**CAP Below**	£19,250.00
Mileage	13,941 Miles Not Warranted	**Body Style**	Panel Van L1	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	30/10/2028	**Gears**	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS, ALLOY WHEELS, HEATED WINDSCREEN & SEATS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos












FORD
e5*2018/858*00192
WF0RXXTA4RSG45199
BJFA
0.50
2825
5325
1550
1550
kg
W(mm)
L(mm)
C
3100
NRN
Ford Motor Company Limited
Arterial Road Laindon Essex,
SS15 6EE United Kingdom










Condition Check



Damage Photos



1: Bumper Front
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
Over 30mm



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint



10: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Not Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK