COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MK65CXB

Vauxhall Vivaro 2700 1.6 CDTI 115PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	31655
Cap Code	VAVI16S575VDTM2 2 L

Details

Location	Doncaster	**VIN**	W0L3F7003FV652823	**CAP Clean**	£1,950.00
Reg. date	01/09/2015	**Body Style**	Panel Van L1	**CAP Average**	£1,600.00
Year	2015	**Service history**	Yes	**CAP Below**	£1,125.00
Mileage	125,710 Miles Warranted	**Service documents**	Printout	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Last service date**	31/10/2026	**Gears**	6
GVW	2740kg	**Last service miles**	125,555		
Colour	GREY	**MOT Due**	31/08/2027		

E/ MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking
- Auxiliary input socket
- Metallic Paint
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos

























Commercial Vehicle Auctions Limited


VANTAGE






Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Insecure
Action Required



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




5: Qtr Panel nsr
Dented
With Paint Damage



6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Dented
Over 30mm



8: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door osf
Dented
With Paint Damage



11: Wing osf
Scratched
Over 25mm Thru Paint



12: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK