COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YX23ATF

FORD / RIMOR KILIG 695 2.0 ECOBLUE 130BHP

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**MOT Due**	27/07/2027
Reg. date	28/03/2023	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2023	**VIN**	WF0DXXTTRDNA01273	**Axle Combi**	4x2
Mileage	30,316 Miles Not Warranted	**Body Style**	Motorhome		

OUTSTANDING RECALL, 6 BERTH, AD BLUE, E/MIRRORS, 4 SEATS WITH 3PT. SEAT BELTS, FRIDGE, FREEZER, OVEN, GAS HOB, SINK, TOILET, SHOWER, OVERHEAD DOUBLE BED, 2 X SINGLE BEDS, REAR STORAGE

Tyres

NSF
NSR
OSF
OSR
Spare


Features

- Bluetooth connection
- USB/iPod interface
- Drivers airbag
- Cruise control
- Manual sunroof
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Digital radio
- Front electric windows
- Cloth seat trim


Photos


















FORD
e1*2007/46*1098
WF0DXXTTRDNA01273
BKFB
0.50
2.0 l HPCR Panther Diesel
130 PS Stage 6.2
350EF
3550 kg
4250 kg
1850 kg
2250 kg
W(mm)
L(mm)
a(mm)
C
3954
FDD









KILIG




Part King


truma
0 100
iNet

MAXVIEW


THETFORD































P
R
N
D
M





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5



3: Qtr Panel nsr
Cracked
Replace



4: Qtr Panel nsr
Cracked
Replace



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Cracked
Replace



7: Bumper Rear
Poor Previous Repair
Poor Paint



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		