COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BD19GGJ

Ford Transit Custom 280 2.0 ECOBLUE 130PS LIMITED

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	42060
Cap Code	FOTU208SL3VDTM2 1 L

Details

Location	Bedford	**GVW**	2800kg	**CAP Clean**	£9,975.00
Reg. date	29/03/2019	**Colour**	BLUE	**CAP Average**	£8,575.00
Year	2019	**VIN**	WF0YXXTTGYJR38177	**CAP Below**	£6,725.00
Mileage	49,015 Miles Warranted	**Body Style**	Panel Van L1	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	14/02/2027	**Gears**	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS, ROOF RACK

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows


Photos















FORD
e1*2007746*1005
WF0YXXTTGYJR38177
YMF6
0.50
30J B
F R
AA A
V6
2800 kg
5240 kg
1575 kg
1415 kg
CUSTOM
LIMITED
PANTHER 20"Wheel
130PS
280S
ST6.6
W(mm)
L(mm)
a(mm)
A
2933
FCC







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Scratched
UpTo 25mm Thru Paint



3: Bumper Front
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Not Thru Paint



6: Seat Base Cover nsf
Holed
Over 3mm



7: B Post ns
Scratched
UpTo 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Sill ns
Dented
With Paint Damage



12: Door nsr
Dented
Over 30mm



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Thru Paint



15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Bumper Rear
Scratched
25 to 100mm Thru Paint



17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Door osf
Chipped
Edge Chip



21: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



22: Seat Base Cover osf
Holed
Over 3mm



23: Seat Base Cover osf
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK