COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE65VAM

DAF LF 220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster
Reg. date	26/10/2015
Year	2015
Mileage	1,038,215 Km Warranted
Fuel Type	DIESEL
GVW	18000kg
Colour	RED

VIN	XLRAEL3700L448468
Body Style	Box Van
Service history	Yes
Service documents	Printout
Last service date	19/08/2025
Last service miles	898,004
MOT Due	31/08/2027

Cab Type	DAY CAB
Gearbox	AUTOMATIC
Axle Combi	4x2
Rear Suspension	Steel
Rear Doors	Roller
Tail Lift	Cantilever

COLLECTED AS NON-RUNNER - CORROSION, TURBO REQUIRES ATTENTION

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim

Photos









14:06 0km/h
OUT 38215.5km

R N D

REPLACEMENT


DAF TRUCKS N.V.








PE65 VAM







Condition Check




Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door Pad osf
Soiled
Heavy



8: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition	Poor	**Upholstery Condition**	Poor
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK