COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YE23OPH

Iveco S-Way 490

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Cab Type**	AS SLEEPER
Reg. date	05/06/2023	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2023	**VIN**	ZCFS62NU50C499724	**Axle Combi**	6x2
Mileage	652,205 Km Not Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Fuel Type	DIESEL	**MOT Due**	31/05/2027	**Rear Suspension**	Air

SLIDING 5TH WHEEL

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Navigation system
- Central locking
- Digital radio
- Cloth seat trim

Photos





















14:55
0km/h
652205.3km
OK
SOFT TURN WARNING CUT-OUT
11pm - 7am ONLY

D
N
R















Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Panel Front
Missing
Replace



3: Panel Front
Chipped
Multiple Chips



4: Panel Front
Missing
Replace




5: Bumper Front Moulding
Broken
Replace



6: Door Mirror Assy nsf
Broken
Replace



7: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



8: Qtr Panel Trim ns
Scuffed
Over 25mm



9: Door osf
Scratched
Over 25mm Thru Paint



10: Door Moulding osf
Broken
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK