COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO21YWC

Mercedes-Benz Sprinter 317 CDI PROGRESSIVE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	49674
Cap Code	MESP2073PGBDTM2 5 L

Details

Location	Bedford	**Colour**	WHITE	**CAP Below**	£5,775.00
Reg. date	31/03/2021	**VIN**	W1V9071352N129454	**Gearbox**	AUTOMATIC
Year	2021	**Body Style**	Dropside L3	**Gears**	6
Mileage	169,880 Miles Warranted	**MOT Due**	02/04/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£7,800.00		
GVW	3500kg	**CAP Average**	£6,950.00		

TAIL LIFT LAST TESTED 11/06/2026

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Air conditioning
- Front electric windows

Photos











R
N
P
D

HIGHWAY
MAINTENANCE
P021 YWC



Mercedes-Benz
MERCEDES-BENZ AG
e1*2007/46*0300
W1V9071352N129454
3500 kg
7000 kg
1650 kg
2250 kg
1-
2-
iHA=3,923
1,0 %
Typ: 906BA35
Made in Germany
A 907 584 32 05
0,12







Condition Check




Damage Photos




1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing nsf
Dented
Between 10mm + 30mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Door nsf
Dented
Over 30mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



8: Seat Base Cover osf
Holed
Over 3mm



9: Centre Console Front
Broken
Replace



10: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK