COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MJ22ESV

Renault Master LM35 ENERGY 2.3 DCI 150PS BUSINESS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Photocopy
Cap Id	45055
Cap Code	R1ML23L30M6DTM2 4 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£7,700.00
Reg. date	10/06/2022	**Colour**	WHITE	**CAP Average**	£7,000.00
Year	2022	**VIN**	VF1MA000567904410	**CAP Below**	£5,900.00
Mileage	93,365 Miles Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
		MOT Due	23/06/2027	**Gears**	6
Fuel Type	DIESEL				

COLLECTED AS NON RUNNER - ENGINE BLOWN, HEAVY SMOKING, WARNING LIGHTS ON DASH, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Navigation system
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag

Photos








93365miles
4645.5miles




















Condition Check



Damage Photos



1: Door Mirror Assy osf
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Sill ns
Dented
With Paint Damage



4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
Over 30mm




7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel Moulding ns
Missing
Replace



10: Qtr Panel nsr
Dented
With Paint Damage



11: Door osr
Dented
With Paint Damage



12: Door osr
Chipped
Multiple Chips



13: C Post os
Chipped
Multiple Chips



14: Qtr Panel osr
Dented
Over 30% Of Panel



15: Qtr Panel osr
Dented
With Paint Damage




16: Qtr Panel Moulding os
Missing
Replace




17: Door osf
Chipped
Multiple Chips



18: Door osf
Dented
With Paint Damage



19: Seat Base Cover nsf
Soiled
Heavy



20: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	Fault		
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault