COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KP71UWU

Vauxhall Movano F3500 CDTI 2.3 Turbo D 150ps

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Photocopy
Cap Id	45425
Cap Code	VAMO2335L06DTM2 3 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£4,650.00
Reg. date	31/12/2021	**VIN**	W0VMR3607MB266308	**CAP Below**	£3,825.00
Year	2021	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
Mileage	128,802 Miles Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	30/12/2026		
GVW	3500kg	**CAP Clean**	£5,225.00		

COLLECTED AS NON-RUNNER - INTERMITTENT LIMP MODE, ENGINE NOISE, WARNING LIGHT ON DASH E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Navigation system
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos










9:39
8°C
128803 miles
2498.2 miles
mph

R 1 3 5
2 4 6





AIRBAG












Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Sill ns
Dented
With Paint Damage



3: Door nsf
Dented
With Paint Damage



4: Door Moulding nsf
Missing
Replace



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel Moulding ns
Missing
Replace




9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Dented
Over 30mm



13: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm




14: Door nsr
Dented
With Paint Damage



15: Door osr
Dented
With Paint Damage



16: Qtr Panel osr
Dented
Over 30mm




17: Qtr Panel osr
Dented
With Paint Damage



18: Door osf
Dented
With Paint Damage



19: Wing osf
Chipped
Multiple Chips



20: Dash Warning Lights
Displayed
No Action



21: Seat Base Cover osf
Holed
Over 3mm



22: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault