COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HT23VYD

Ford Transit 350 2.0 EcoBlue 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45297
Cap Code	FOTR2035331DTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£19,050.00
Reg. date	27/07/2023	**Colour**	WHITE	**CAP Average**	£17,650.00
Year	2023	**VIN**	WF0CXXTTRCPK63261	**CAP Below**	£15,200.00
Mileage	34,984 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	29/07/2027	**Gears**	6

AD BLUE, TOW BAR

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim
- Front electric windows

Photos










TRANSIT
BASE
2.0 l HPCR Duratorq Diesel
130 PS
Stage 6.2
350L
BKRA
0.50
FORD
e1*2007/46*1096
* WF0CXXTTRCPK63261
3500
6500
1850
2450
W(mm)
H
3954
L(mm)
FED



Raise
Lower
ON
Isolation switch
ON

PF Jones
Part No: TFO201



WF0CXXTTRCPK63261
STAGE 2
e11*2007/46*1563*08
VFS (Southampton) Ltd
8 Barton Park Ind Est.
Eastleigh, Hants,




R 1 3 5
2 4 6

Ford
AIRBAG






Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Wheel nsf
Corroded
Light



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: A Post ns
Scratched
Over 25mm Not Thru Paint




8: Door nsf
Chipped
Over 5mm



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Fuel Flap
Scratched
Over 25mm Not Thru Paint



12: Door nsr
Scratched
Over 25mm Not Thru Paint



13: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



14: Door nsr
Scratched
Over 25mm Thru Paint



15: D Post ns
Chipped
Over 5mm



16: D Post ns
Scratched
Over 25mm Not Thru Paint



17: D Post os
Scratched
Over 25mm Not Thru Paint



18: D Post os
Chipped
Over 5mm



19: Door osr
Chipped
Over 5mm



20: Door osf
Chipped
Over 5mm



21: Door osf
Scratched
Over 25mm Not Thru Paint



22: Sill os
Dented
With Paint Damage



23: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



24: Bumper Front
Scratched
Over 25mm Not Thru Paint



25: Bumper Front
Scratched
Over 25mm Not Thru Paint



26: Headrest Assy osf
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK