COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CJ22FNT

Citroen C4 1.2 PURETECH 130PS SHINE

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present
Cap Id	94976
Cap Code	CIC412SP35HPTA 3

Details

Location	Bedford	**Colour**	GREY	**CAP Below**	£7,275.00
Reg. date	31/08/2022	**VIN**	VR7BAHNSBNE047182	**Gearbox**	AUTOMATIC
Year	2022	**Body Style**	Hatchback	**Gears**	8
Mileage	44,550 Miles Not Warranted	**MOT Due**	16/07/2027	**Doors**	5
Fuel Type	PETROL	**CAP Clean**	£9,350.00		
GVW	1755kg	**CAP Average**	£8,325.00		

SPARE WHEEL, E/MIRRORS, DUAL ZONE CLIMATE CONTROL, HEATED SEATS, KEYLESS IGNITION

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Air conditioning
- Alloy wheels
- Park assist camera
- Front electric windows
- Rear parking sensor
- Rear electric windows
- Body coloured bumpers
- Leather seat trim

Photos












PSA AUTOMOBILES SA
VR7BAHNSB
1755 KG
2955 KG
1-970 KG
2-970 KG
2-10 BOULEVARD DE L'EUROPE
78300 POISSY(FRANCE)
CITROEN
Pression pneu froid / Cold tire pressure / Reifendruck kalt /
195/60 R18 96H


CJ22 FNT





CJ22 FNT









OUTSIDE


Condition Check



Damage Photos



1: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK

		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK