COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LM67KFL

Ford Transit 350 2.0 TDCI 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38011
Cap Code	FOTR20L230BDTM2 4 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£5,225.00
Reg. date	21/11/2017	**Colour**	GREEN	**CAP Average**	£4,375.00
Year	2017	**VIN**	WF0DXXTTGDHR02886	**CAP Below**	£3,275.00
Mileage	170,680 Miles Warranted	**Body Style**	Tipper L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

TIPPER IN-OP

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Front electric windows


Photos














LM67 KFL


FORD
TRANSIT
BASE
2500
5500
1750
2150
3504
FED






Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK