COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR67CSV

Ford Transit 350 2.0 TDCI 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38011
Cap Code	FOTR20L230BDTM2 4 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£6,525.00
Reg. date	31/10/2017	**Colour**	GREEN	**CAP Average**	£5,450.00
Year	2017	**VIN**	WF0DXXTTGDHR02885	**CAP Below**	£4,050.00
Mileage	125,546 Miles Warranted	**Body Style**	Tipper L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

WARNING LIGHTS ON DASH, VEHICLE INTERMITENTLY CUTS OUT WHEN DRIVING TOW BAR, AD BLUE, SPARE WHEEL

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Front electric windows

Photos






















Commercial Vehicle Auctions Limited

Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Wing Front Arch Extension os
Broken
Replace



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bonnet
Dented
Over 2 UpTo 10mm



5: Front TowEye Cvr
Missing
Replace



6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Panel Front
Scratched
UpTo 25mm Thru Paint



8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



17: Seat Base Cover osf
Holed
Over 3mm



18: Seat Base Cover osf
Holed
Over 3mm



19: Sill os
Rusted
Over 5mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No
Engine Runs	Fault		

Commercial Vehicle Auctions Limited