COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**MF73ENO**

## Iveco Daily 35-140

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Buyer To Apply |
| **Cap Id** | 46824 |
| **Cap Code** | IVDA235S44BDTM2 5 L |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Bedford | **Colour** | WHITE | **CAP Below** | £10,650.00 |
| **Reg. date** | 08/09/2023 | **VIN** | ZCFCL35A00D739958 | **Gearbox** | MANUAL |
| **Year** | 2023 | **Body Style** | Dropside LWB | **Gears** | 6 |
| **Mileage** | 61,303 Miles Not Warranted | **MOT Due** | 09/09/2027 | **Tail Lift** | Column |
| **Fuel Type** | DIESEL | **CAP Clean** | £13,350.00 | | |
| **GVW** | 3500kg | **CAP Average** | £12,400.00 | | |

*WARNING LIGHT ON DASH, TAIL LIFT STUCK IN DOWN POSITION* 3750 WB, E/MIRRORS, AD BLUE

### Tyres

| | |
|---|---|
| **NSF** | |
| **NSR** | |
| **OSF** | |
| **OSR** | |
| **Spare** | |

## Features

- Park assist camera
- Air conditioning
- Front electric windows

## Photos
















WWW.BT-BS.COM


IVECO SpA
Manufacturer name and address: IVECO S.p.A. Via Puglia 35 - 10156 Torino - ITALY
e3*2007/46*0118*
ZCFCL35A00D739958
3500 kg
7000 kg
1 - 1900 kg
2 - 2240 kg
Type IS35SI2AA
Wheelbase 3750
N° of axles 2
Engine Type F1AGL411B
Engine power kW 100





# Condition Check




## Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Dented
Between 10mm + 30mm




3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
Over 10mm



5: Bonnet
Scratched
Over 25mm Not Thru Paint



6: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Flasher Side Repeater ns
Broken
Replace



9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Dented
Over 30mm



12: Door osf
Scratched
Over 25mm Not Thru Paint

## Interior

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | Fault | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |