COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WG71VNV

Ford Ranger Wildtrak 2.0 EcoBlue 213

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44067
Cap Code	FORA20WILD7DTA4 6 L

Details

Location	Livingston	**GVW**	3270kg	**CAP Clean**	£14,950.00
Reg. date	14/01/2022	**Colour**	WHITE	**CAP Average**	£13,600.00
Year	2022	**VIN**	6FPPXXMJ2PMK43497	**CAP Below**	£11,400.00
Mileage	49,877 Miles Not Warranted	**Body Style**	Pickup Double Cab	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**MOT Due**	29/03/2027	**Gears**	1

TOW BAR, ROOF RACK, E/MIRRORS, LEATHER, REAR VIEW CAMERA, HEATED WINDSCREEN, AD-BLUE.

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Front parking sensor
- Radio/CD
- Heated front seat
- Air conditioning
- Navigation system
- Central locking
- Rear parking sensor


Photos















RANGER
WG71 VNV


FORD
e5*2007/46*0080
6FPPXXMJ2PMK43497
3270 KG
6000 KG
1480 KG
1850 KG
VIN
MADE IN SOUTH AFRICA















Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door osf
Dented
With Paint Damage



4: Qtr Panel nsr
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK