COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BL73AVN

Ford Transit 350 2.0 ECOBLUE130PS LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58952
Cap Code	FOTR203L31DDTM2 5 L

Details

Location	Avonmouth	**Colour**	WHITE	**CAP Below**	£11,100.00
Reg. date	09/02/2024	**VIN**	WF0AXXTTRAPS10920	**Gearbox**	MANUAL
Year	2024	**Body Style**	Dropside	**Gears**	6
Mileage	58,827 Miles Not Warranted	**MOT Due**	08/02/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£13,350.00		
GVW	3500kg	**CAP Average**	£12,600.00		

CRACKED WINDSCREEN AD BLUE, TWIN SIDE LOAD DOORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Navigation system
- Mobile phone App interface
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Central locking
- Auxiliary input socket
- Air conditioning
- Cloth seat trim

Photos












58828.1 mls
21.5 mpg
3792.5 mls
0.1 gal/h
59 mls



Ford
AIRBAG


TRANSIT
BASE
2.0 I HPCR Panther Diesel
130 PS Stage 6.2
350L
BKFB
0.50
FORD
e1*2007/46*1096
WF0AXXTTRAPS10920
3500 kg
5065 kg
1750 kg
2250 kg
W(mm)
J 3954
L(mm)
a(mm)
FED


PALFINGER
PALFINGER



WWW.BT-HE.COM

MENU
CAM
MODE
POWER

R 1 3 5
2 4 6

TAIL LIFT










Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Bonnet
Chipped
Over 5mm



3: Bumper Front
Scratched
Over 25mm Not Thru Paint




4: Door Mirror Assy nsf
Broken
Replace




5: Bumper Front
Scratched
Over 25mm Not Thru Paint




6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: B Post ns
Scratched
Over 25mm Not Thru Paint



8: B Post os
Scratched
Over 25mm Not Thru Paint



9: Door osf
Scratched
Over 25mm Not Thru Paint



10: Door osf
Chipped
Over 5mm



11: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



12: Roof
Chipped
Over 5mm



13: Bumper Front
Scratched
Over 25mm Not Thru Paint



14: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK		