COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HG23DDZ

Ford / Roller Team AUTO ROLLER 747 2.0 ECOBLUE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Bedford	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	24/05/2023	**GVW**	3500kg	**MOT Due**	22/07/2027
Year	2023	**Colour**	WHITE	**Gearbox**	MANUAL
Mileage	35,482 Miles Not Warranted	**VIN**	WF0DXXTTRDNB39113		

6 BERTH, 6 SEATS WITH 3PT. SEATBELTS, AD BLUE, HEATED WINDSCREEN, E/MIRRORS,3 RING HOB, OVEN, FRIDGE, SINK, TOILET, SEATING AREA, DROP DOWN DOUBLE BED, FOLD OUT DOUBLE BED, SEATING AREA

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Navigation system
- Central locking
- Park assist camera
- Air conditioning
- Front electric windows


Photos











ROLLER TEAM
AUTO-ROLLER
HG23 DDZ

HG23 DDZ

TRANSIT
CAMPER
2.0 I HPCR Panther Diesel
170 PS Stage 6.2
350EF
BLFB
0.50
FORD
e1*2007/46*1098
WF0DXXTTRDNB39113
3550 kg
5065 kg
1850 kg
2250 kg
W(mm)
L(mm)
a(mm)
J 3954
FDD


1 X































35482.7 mls
7°
28.2 mpg
9757.9 mls
0.1 gal/h
124 mls





Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



2: Flasher Side Repeater os
Broken
Replace



3: Door Mirror Glass os
Missing
Replace



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



7: Seat Base Cover osf
Holed
Over 3mm



8: Seat Base Cover nsr
Torn
Over 3mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK