COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ25VWL

Ford / Roller Team ZEFIRO 675 2.0 ECOBLUE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Bedford	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	03/04/2025	**GVW**	3500kg	**MOT Due**	02/04/2028
Year	2025	**Colour**	WHITE	**Gearbox**	MANUAL
Mileage	21,393 Miles Not Warranted	**VIN**	WF0DXXTTRDSJ34825		

OUTSTANDING RECALL 6 BERTH, 6 SEATS WITH 3PT SEATBELTS AD BLUE, E/MIRRORS, HEATED WINDSCREEN, SINK, 3 RING HOB, OVEN, TOILET, BUNK BEDS, OVERHEAD DOUBLE BED, BIKE RACK, REAR STORAGE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Navigation system
- Park assist camera
- Air conditioning
- Front electric windows


Photos










ROLLER TEAM
HJ25 VWL



FORD
e1*2007/46*1098
WF0DXXTTRDSJ34825
BKFB
0.50
3550 kg
5700 kg
2000 kg
2250 kg
W(mm)
L(mm)
a(mm)
L 3750
FDD
Ford Motor Company Limited
Arterial Road, Laindon, Essex,
SS15 6EE United Kingdom


675

675






























NE
0
mph
120
60
21393.8
8°
37





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Flasher Side Repeater ns
Broken
Replace



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Fog Lamp Surround os
Broken
Replace



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel Trim os
Broken
Replace



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK