COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ23EAA

Fiat / Roller Team AUTO-ROLLER 707 Ducato 2.3 MULTIJET 140PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	46244
Cap Code	FIDU2335L4BDTA2 5 L

Details

Location	Bedford	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	24/05/2023	**GVW**	3500kg	**MOT Due**	10/06/2027
Year	2023	**Colour**	WHITE	**Gearbox**	SEMI AUTO
Mileage	41,419 Miles Not Warranted	**VIN**	ZFA25000002W75066	**Gears**	6

6 BERTH, 6 SEATS WITH 3PT. SEATBELTS, AD BLUE, E/MIRRORS, HEATED WINDSCREEN, TOILET, HOB, SINK, OVEN, SEATING AREA, BUNK BEDS, BIKE RACK, REAR STORAGE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Photos














ROLLER TEAM
AUTO-ROLLER
HJ23 EAA

AUTO


CORSO G.AGNELLI 200
10135 TORINO - ITALY
FCA ITALY S.P.A.
C3*2007746*0049
*ZFA250000*02M750666*
3650 KG KG
6150 KG KG
1= 1960 KG
2= 2000 KG
MOTORE 46349131
VERSIONE 250GTBAU ABCS1
MADE IN ITALY 0,50
2894


AUTO




























Speedometer
MPH





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



4: Bumper Rear Moulding
Scratched (Painted)
UpTo 25mm Not Thru Paint



5: Bumper Rear
Cracked
UpTo 25mm



6: Fog Lamp Surround os
Broken
Replace



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel osr
Dented
With Paint Damage



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Seat Base Cover nsf
Scuffed
UpTo 25mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK