COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BG24MHX

Ford Transit 350 2.0 EcoBlue 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44615
Cap Code	FOTR20L3L3HDTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£14,600.00
Reg. date	30/04/2024	**Colour**	WHITE	**CAP Average**	£13,750.00
Year	2024	**VIN**	WF0EXXTTRERB64446	**CAP Below**	£12,100.00
Mileage	42,731 Miles Not Warranted	**Body Style**	Panel Van L4	**Gearbox**	MANUAL
		MOT Due	29/04/2027	**Gears**	6
Fuel Type	DIESEL				

WARNING LIGHT ON DASH, OUTSTANDING RECALL, AD BLUE, SIDE LOAD DOOR

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim
- Front electric windows

Photos







TRANSIT
BASE
2.0 l HPCR Panther Diesel
130 PS Stage 6.2
350EF
BKRA
0.50
FORD
e1*2007/46*1100
* WF0EXXTTRERB64446 *
3500
5550
1750
2250
W(mm)
L(mm)
a(mm)
B 3750
FCD





Ford

R 1 3 5
2 4 6





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: A Post ns
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
Over 5mm



9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Lamp nsr
Broken
Replace



13: Tailgate
Dented
Over 30mm



14: Roof
Dented
Over 30mm



15: Tailgate
Dented
With Paint Damage



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel osr
Dented
With Paint Damage




19: Door osf
Chipped
Over 5mm



20: Door nsf
Scratched
Over 25mm Not Thru Paint



21: Door Mirror Assy osf
Broken
Replace



22: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK