COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PN72BKX

Fiat Ducato 35 2.2 MULTIJET 120PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	52209
Cap Code	FIDU22302SVDTM2 5 L

Details

Location	Bedford	**Colour**	MULTI-COLOURED	**CAP Below**	£5,150.00
Reg. date	28/10/2022	**VIN**	ZFA25000002U80232	**Gearbox**	MANUAL
Year	2022	**Body Style**	Dropside SWB	**Gears**	6
Mileage	63,618 Miles Warranted	**MOT Due**	Expired	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£6,750.00		
GVW	3000kg	**CAP Average**	£6,125.00		

NEEDS NEW TURBO, TAIL LIFT IN-OP E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Air conditioning
- Front electric windows

Photos











PN72 BKX


PN72 BKX

FCA ITALY S.P.A.
e3*2007/46*0044
*ZFA250D00*02U80232*
3500 KG KG
6500 KG KG
1- 2100 KG
2- 2400 KG
MOTORE 46349131
VERSIONE 250DTNAU GE
MADE IN ITALY 0.50
2894





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Grille Front
Missing
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Bonnet
Scratched
UpTo 25mm Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Door Mirror Assy nsf
Broken
Replace



8: Door Mirror Glass ns
Broken
Replace



9: Door nsf
Dented
With Paint Damage



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
UpTo 25mm Thru Paint



14: Door osf
Dented
With Paint Damage



15: Door Mirror Assy osf
Broken
Replace



16: Centre Console Front
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK