COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK67VZT

Man TGM 18.250

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Code	999900

Details

Location	Bedford	**GVW**	18000kg	**Cab Type**	DAY CAB
Reg. date	27/02/2018	**Colour**	BLUE	**Gearbox**	AUTOMATIC
Year	2018	**VIN**	WMAN08ZZ1JY368943	**Axle Combi**	4x2
Mileage	277,971 Km Warranted	**Body Style**	Dropside & Crane	**Rear Suspension**	Steel
Fuel Type	Diesel	**MOT Due**	30/09/2027		

SERVICE SCHEDULE LIST AVAILABLE, HIAB X-HIDOU 138 REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM

Tyres


NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Park assist camera

Photos












09:42 0 0km/h
OUT 277972.0km




Plate
WMAN08ZZ1JY368943
MAN /TGM 18.250 4X2 BB
RIGID
27/02/18
2017
Gross Weight
18000
18000
9706
2490
Train Weight
Max. Train Weight
Axle 1
7500
7500
Axle 2
11500
11500
Axle 3
Axle 4
DEPARTMENT FOR
07/03/23
TRANSPORT
GREAT BRITAIN
REPLACEMENT


WMAN08ZZ1JY368943
MAN Truck & Bus AG
e4*2007/46*0238
WMAN08ZZ1JY368943
(GB)
18000kg 18000kg
0kg 0kg
1 7500kg 7500kg
2 11500kg 11500kg
E4*2007/46*0238*
MAN
ERC









MODE
MENU




X-HIDUO T38




HIAB
911-7288
4721




MAN










Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing osf
Cracked
Replace



3: A Post os
Scratched
UpTo 25mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
Edge Chip



8: Wing nsf
Poor Previous Repair
Poor Colour



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Rusted
Over 5mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



13: Door osf
Chipped
Edge Chip



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Seat Base Cover osf
Holed
Over 3mm



16: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK