COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MA22SPV

Ford Ranger 2.0 ECOBLUE 170PS LIMITED

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44061
Cap Code	FORA20LD 7DTA4 6 L

Details

Location	Bedford	**Colour**	WHITE	**CAP Below**	£9,800.00
Reg. date	18/03/2022	**VIN**	6FPPXXMJ2PMD52743	**Gearbox**	AUTOMATIC
Year	2022	**Body Style**	Pickup Double Cab	**Gears**	1
Mileage	57,009 Miles Not Warranted	**MOT Due**	01/04/2027	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£12,800.00		
GVW	3270kg	**CAP Average**	£11,650.00		

WARNING LIGHT ON DASH TOW BAR

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Leather seat trim
- Rear parking sensor
- Air conditioning


Photos















FORD
e5*2007/46*0080
6FPPXXMJ2PMD52743
3270 KG
6000 KG
1480 KG
1850 KG
VIN
2AB
0.50
MADE IN SOUTH AFRICA







Entertainment
Phone
P R N D S





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Wing osf
Dented
With Paint Damage



4: Bumper Front
Chipped
Multiple Chips



5: Flasher Side Repeater ns
Broken
Replace



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Roof
Rusted
UpTo 5mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK