COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LG24NAC

Citroen Relay 35 2.2 BlueHDI 140

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	58322
Cap Code	CIRE2235H4HDTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£14,700.00
Reg. date	31/08/2024	**Colour**	WHITE	**CAP Average**	£13,850.00
Year	2024	**VIN**	VF7YDF6F6RG053011	**CAP Below**	£12,200.00
Mileage	39,100 Miles Not Warranted	**Body Style**	Panel Van L4	**Gearbox**	MANUAL
		MOT Due	30/08/2027	**Gears**	6
Fuel Type	DIESEL				

WARNING LIGHTS ON DASH, DRIVERS DOOR DOES NOT OPEN, OUTSTANDING RECALL, AD BLUE, SIDE LOAD DOOR E/MIRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Digital radio
- Drivers airbag
- Cruise control
- USB/iPod interface
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Auxiliary input socket
- Front electric windows
- Cloth seat trim

Photos










AUTOMOBILES CITROEN
VF7YDF6F6RG053011







R 1 3 5
2 4 6





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Bonnet
Dented
Over 30mm



4: Bumper Front
Cracked
Over 25mm



5: Wing nsf
Chipped
Over 5mm



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Over 5mm



9: B Post ns
Missing
Replace



10: Door nsr
Chipped
Over 5mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel Moulding ns
Broken
Replace



14: Bumper Rear
Hole
Over 25mm



15: Bumper Rear
Missing
Replace



16: Tailgate
Dented
Over 30mm



17: Tailgate
Dented
Over 30mm



18: Tailgate
Chipped
Edge Chip



19: Lamp nsr
Broken
Replace



20: Bumper Rear
Hole
Over 25mm



21: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



22: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



23: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



24: Qtr Panel osr
Chipped
Over 5mm



25: Qtr Panel osr
Dented
With Paint Damage



26: Door osf
Dented
With Paint Damage



27: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



28: Wing osf
Missing
Replace



29: Bumper Front
Scratched
Over 25mm Not Thru Paint



30: Grille Front
Broken
Replace



31: Door Pad osf
Broken
Replace



32: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK