COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LG24THL

Citroen Relay 35 2.2 BlueHDI 140PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	58322
Cap Code	CIRE2235H4HDTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£13,850.00
Reg. date	30/08/2024	**Colour**	WHITE	**CAP Average**	£13,050.00
Year	2024	**VIN**	VF7YDF6F4RG053010	**CAP Below**	£11,500.00
Mileage	49,003 Miles Not Warranted	**Body Style**	Panel Van L4	**Gearbox**	MANUAL
		MOT Due	29/08/2027	**Gears**	6
Fuel Type	DIESEL				

OUTSTANDING RECALL, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Auxiliary input socket
- Front electric windows
- Cloth seat trim
- Cruise control
- Digital radio
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Passenger airbag
- Rear parking sensor
- Air conditioning
- Central locking


Photos








AUTOMOBILES CITROEN
VF7YDF6F4RG053010
3500 KG
6500 KG
1 – 2100 KG
2 – 2400 KG
0,51



RADIO
MEDIA
VOL


R 1 3 5
4H
2 4 6





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Dented
Over 30% Of Panel



5: Door Mirror Assy nsf
Broken
Replace



6: Wheel nsf
Corroded
Light



7: Door nsf
Chipped
Over 5mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: B Post ns
Scratched
Over 25mm Thru Paint



10: Door nsr
Chipped
Edge Chip



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel Moulding ns
Broken
Replace



13: Sill ns
Dented
Over 30mm



14: Sill ns
Dented
Over 30mm



15: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



16: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



17: Lamp nsr
Broken
Replace



18: Tailgate
Dented
Over 30mm



19: Tailgate
Scratched
Over 25mm Thru Paint



20: Tailgate
Chipped
Edge Chip



21: Tailgate
Chipped
Over 5mm



22: D Post os
Dented
With Paint Damage



23: Qtr Panel osr
Scratched
Over 25mm Thru Paint



24: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



25: Qtr Panel osr
Chipped
Over 5mm



26: Qtr Panel osr
Chipped
Over 5mm



27: Door osf
Chipped
Over 5mm



28: Door osf
Chipped
Edge Chip



29: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



30: Wing osf
Dented
Over 30mm



31: Bumper Front
Scratched
Over 25mm Not Thru Paint



32: Bumper Front
Hole
Over 25mm



33: Roof
Dented
Over 30% Of Panel



34: A Post ns
Rusted
Over 5mm



35: Carpets Front
Holed
Over 3mm



36: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited