COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MF23CKA

IVECO DAILY 35-140

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	46824
Cap Code	IVDA235S44DDTM2 5 L

Details

Location	Avonmouth	**Colour**	WHITE	**CAP Below**	£8,750.00
Reg. date	25/08/2023	**VIN**	ZCFCL35A10D732288	**Gearbox**	MANUAL
Year	2023	**Body Style**	Dropside	**Gears**	6
Mileage	90,302 Miles Not Warranted	**MOT Due**	13/09/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£11,000.00		
GVW	3500kg	**CAP Average**	£10,200.00		

AD BLUE, E/MIRRORS, 3750 WB

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Auxiliary input socket
- Air conditioning
- Cloth seat trim
- Cruise control
- Digital radio
- Front electric windows
- Navigation system
- Mobile phone App interface
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Central locking


Photos











IVECO SpA
e3*2007/46*0118*
ZCFCL35A10D732288
3500 kg
7000 kg
1 - 1900 kg
2 - 2240 kg
Type IS35SI2AA
Wheelbase 3750
Engine Type F1AGL411B
100
0.502


PALFINGER
PALFINGER



DAB BBC R2
14:47
Bristol
DAILY


IVECO
AIR bag








Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Wheel nsf
Corroded
Light



7: Door nsf
Chipped
Over 5mm




8: Wheel nsr
Corroded
Light



9: Bumper Rear
Rusted
Over 5mm



10: Wheel osr
Corroded
Light



11: B Post os
Chipped
Over 5mm



12: Door osf
Chipped
Over 5mm



13: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



14: Wheel osf
Corroded
Light



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



16: Bumper Front
Chipped
Over 5mm



17: Bonnet
Chipped
Over 5mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK		

Commercial Vehicle Auctions Limited