COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SF23PZP

Fiat Ducato 35 2.2 MULTIJT 140PS BUSINESS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	57370
Cap Code	FIDU22MBP HDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£8,700.00
Reg. date	31/03/2023	**Colour**	WHITE	**CAP Average**	£8,050.00
Year	2023	**VIN**	ZFA25000002W81913	**CAP Below**	£6,925.00
Mileage	65,772 Miles Not Warranted	**Body Style**	Panel Van MWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	30/03/2027	**Gears**	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features




- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows


Photos









FCA ITALY S.P.A.
ZFA250000
3500 KG
6000 KG
1870 KG
2000 KG
MOTORE 4H03
MADE IN ITALY




Range 157 mi




Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm



4: Front TowEye Cvr
Missing
Replace



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



7: Wing nsf
Chipped
Multiple Chips



8: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Door nsr
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



13: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



14: Door nsr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Scratched
UpTo 25mm Thru Paint



16: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



17: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



18: Door osr
Dented
With Paint Damage



19: Qtr Panel osr
Dented
With Paint Damage



20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



21: Qtr Panel osr
Dented
With Paint Damage



22: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



23: Door osf
Chipped
Edge Chip



24: Carpets Front
Holed
Over 3mm



25: Roof
Dented
With Paint Damage

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK