COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ67WMF

Daf CF 450

Non Runner

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Livingston	**GVW**	44000kg	**Cab Type**	SLEEPER CAB
Reg. date	27/02/2018	**Colour**	RED	**Gearbox**	AUTOMATIC
Year	2018	**VIN**	XLRTGM4100G186948	**Axle Combi**	4x2
Mileage	1,321,357 Km Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift Steer
Fuel Type	DIESEL	**MOT Due**	31/03/2027	**Rear Suspension**	Air

NON-RUNNER- GEAR BOX STRIPPED, SEVERE OIL LEAK - GASKET SET, TURBO, FLEXI PIPES, EGR VALVE & HARNESS REQUIRE ATTENTION

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Radio/CD
- Air conditioning

Photos














OPERATION
321357.0km


PJ67 WMF
DAF


DEPARTMENT FOR TRANSPORT GREAT BRITAIN


DAF TRUCKS N.V.
GB
XLRTGM4100G186948
ADR4
Type
Motor no.















Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing osf
Chipped
Multiple Chips



4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Rusted
Over 5mm



6: Wing nsf
Chipped
Multiple Chips



7: Door nsf
Dented
Over 30mm



8: Door Moulding nsf
Broken
Replace



9: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	Fault	No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	Fault