COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SF23PZM

Fiat Ducato 2.2 MULTIJET 140PS BUSINESS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	57370
Cap Code	FIDU22MBP HDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£8,925.00
Reg. date	31/03/2023	**Colour**	WHITE	**CAP Average**	£8,275.00
Year	2023	**VIN**	ZFA25000002W83238	**CAP Below**	£7,125.00
Mileage	60,769 Miles Not Warranted	**Body Style**	Panel Van MWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	08/04/2027	**Gears**	6

WARNING LIGHT ON DASH AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows


Photos








CORSO G.AGNELLI 200
10135 TORINO - ITALY
FCA ITALY S.P.A.
3500 KG
6000 KG
1870 KG
2000 KG
MOTORE 4H03







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
Multiple Chips



3: Roof
Dented
Between 10mm + 30mm



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Qtr Panel osr
Dented
With Paint Damage



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK