COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SF23RCY

Fiat Ducato 2.2 MULTIJET 140PS BUSINESS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	57371
Cap Code	FIDU22LBP HDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£10,650.00
Reg. date	31/03/2023	**Colour**	WHITE	**CAP Average**	£9,850.00
Year	2023	**VIN**	ZFA25000002W83081	**CAP Below**	£8,475.00
Mileage	34,082 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	30/03/2027	**Gears**	6

INTERMITENT WARNING LIGHT ON DASH, SIDE DOOR IN-OP AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos








CORSO G.AGNELLI 200
10135 TORINO ITALY
FCA ITALY S.P.A.
3500 KG
6000 KG
1 1870 KG
2 2000 KG
MOTORE 4H03






Condition Check



Damage Photos



1: Roof
Dented
Over 2 UpTo 10mm



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm




5: Door nsr
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Door Moulding osr
Broken
Replace



12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel osr
Dented
With Paint Damage




14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault