COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

EA71WNC

Ford Transit Custom 300 2.0 ECOBLUE 130PS LEADER

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44484
Cap Code	FOTU200L3LVDTM2 1 L

Details

Location	Bedford	**GVW**	3000kg	**CAP Clean**	£8,900.00
Reg. date	06/01/2022	**Colour**	WHITE	**CAP Average**	£8,075.00
Year	2022	**VIN**	WF0YXXTTGYMG38797	**CAP Below**	£6,775.00
Mileage	Not Showing	**Body Style**	Fridge Van L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	10/01/2027	**Gears**	6

NON RUNNER-DOES NOT POWER UP, PARTS STRIPPED GAH UNIT, SIDE LOADING DOOR, MOT SHOWS 63,813 MILES 07/01/2026

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front electric windows


Photos












FORD
e1*2007/46*1005
WF0YXXTTGYMG38797
3000
5240
1675
1590
CUSTOM
BASE
2.0 HPCR PANTHER Diesel
130PS
STAGE 6.2
300L
BKFB
0.50
W(mm)
L(mm)
a(mm)
F
3300
Fcc












Condition Check



Damage Photos



1: Bonnet
Missing
Replace



2: Bumper Front
Missing
Replace



3: Grille Front
Missing
Replace



4: Headlamp os
Missing
Replace



5: Headlamp ns
Missing
Replace



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Hole
UpTo 25mm



10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No
Engine Runs	Fault		