COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

EA71WNE

Ford Transit Custom 300 2.0 ECOBLUE 130PS LEADER

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44484
Cap Code	FOTU200L3LVDTM2 1 L

Details

Location	Bedford	**GVW**	3000kg	**CAP Clean**	£8,650.00
Reg. date	06/01/2022	**Colour**	WHITE	**CAP Average**	£7,850.00
Year	2022	**VIN**	WF0YXXTTGYMG38801	**CAP Below**	£6,600.00
Mileage	74,410 Miles Not Warranted	**Body Style**	Fridge Van L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	12/01/2027	**Gears**	6

ONLY RUNS WITH JUMP PACK ATTACHED, ENGINE KNOCKING GAH UNIT, SIDE LOADING DOOR

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front electric windows

Photos














FORD







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Insecure
Action Required



4: Bumper Front
Cracked
UpTo 25mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Over 30mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Door osr
Scratched
UpTo 25mm Thru Paint



11: Lamp osr
Broken
Replace



12: Door nsr
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Dented
With Paint Damage



14: Qtr Panel osr
Dented
With Paint Damage



15: Sill os
Dented
With Paint Damage



16: Door osf
Chipped
Edge Chip



17: Door osf
Scratched
Over 25mm Thru Paint



18: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



19: Seat Base Cover osf
Holed
Over 3mm



20: Seat Base Cover osf
Burn
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK