COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SA71KJO

Fiat Doblo 1.6 MULTIJET 16V

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	34197
Cap Code	FIDO16WSS DDTM2 4 L

Details

Location	Bedford	**Fuel Type**	DIESEL	**Body Style**	Dropside L2
Reg. date	22/11/2021	**GVW**	2510kg	**Gearbox**	MANUAL
Year	2021	**Colour**	WHITE	**Gears**	5
Mileage	Not Showing	**VIN**	ZFA26300006V27271		

NON RUNNER-ENGINE & PARTS STRIPPED, DOES NOT POWER UP AD BLUE, MOT DOES NOT SHOW PREVIOUS MILEAGE

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front electric windows

Photos













SA71KJO

FCA ITALY S.P.A.
ZFA26300006V27271
0.51
MOTORE – ENGINE
55280444
VERSIONE – VERSION
263HXX1B LR2F5
MADE IN TURKEY











Condition Check



Damage Photos




1: Wing osf
Scratched
UpTo 25mm Not Thru Paint



2: Bumper Front
Missing
Replace



3: Grille Front
Missing
Replace



4: Headlamp ns
Missing
Replace



5: Bonnet
Dented
Over 30mm



6: Wing nsf
Dented
With Paint Damage



7: Moulding nsf Wing
Missing
Replace



8: Door Mirror Assy nsf
Broken
Replace



9: Door nsf
Dented
With Paint Damage



10: B Post ns
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
Over 30mm



12: Bumper Rear
Dented
Over 30mm



13: Tailgate
Hole
Over 10mm



14: Sill os
Dented
With Paint Damage



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Number Plate Front
Missing
Replace




18: Seat Base Cover osf
Holed
Over 3mm



19: Seat Back Cover osf
Holed
Over 3mm



20: Fascia Trim
Damaged
Replace



21: Centre Console Front
Broken
Replace



22: Air Vents osf
Missing
Replace



23: Seat Belt nsf
Missing
Replace



24: Seat Belt osf
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No
Engine Runs	Fault		