COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SA71KJE

Fiat Doblo 1.6 MULTIJET 16V

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	34197
Cap Code	FIDO16WSS DDTM2 4 L

Details

Location	Bedford	**GVW**	2510kg	**CAP Clean**	£5,400.00
Reg. date	07/12/2021	**Colour**	WHITE	**CAP Average**	£4,825.00
Year	2021	**VIN**	ZFA26300006V29580	**CAP Below**	£3,950.00
Mileage	Not Showing	**Body Style**	Dropside L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	5

NON RUNNER-ENGINE & PARTS STRIPPED, DOES NOT POWER UP AD BLUE, MOT SHOWS 62,222 MILES 04/12/2024

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front electric windows

Photos












SA71 KJE


FCA ITALY S.P.A.
ZFA26300006V29580
0.51
MADE IN TURKEY








Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Grille Front
Missing
Replace



3: Bumper Front
Missing
Replace



4: Number Plate Front
Missing
Replace



5: Headlamp os
Broken
Replace



6: Headlamp ns
Broken
Replace



7: Wing nsf
Dented
With Paint Damage



8: Bonnet
Dented
Over 30mm



9: Door Mirror Assy nsf
Broken
Replace



10: Qtr Panel nsr
Dented
Over 30mm



11: Tailgate
Hole
Over 10mm



12: Lamp nsr
Broken
Replace



13: Tailgate
Poor Previous Repair
Poor Paint



14: Lamp osr
Broken
Replace



15: Flasher Side Repeater os
Broken
Replace



16: Seat Base Cover osf
Holed
Over 3mm



17: Seat Back Cover osf
Holed
Over 3mm



18: Fascia Panel
Missing
Replace



19: Air Vents osf
Damaged
Replace



20: Switches And Controls
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No
Engine Runs	Fault		

Commercial Vehicle Auctions Limited