COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

NX71VXL

Fiat Doblo 1.6 MULTIJET 16V

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	34197
Cap Code	FIDO16WSS DDTM2 4 L

Details

Location	Bedford	**GVW**	2510kg	**CAP Clean**	£5,400.00
Reg. date	10/12/2021	**Colour**	WHITE	**CAP Average**	£4,825.00
Year	2021	**VIN**	ZFA26300006V33833	**CAP Below**	£3,950.00
Mileage	Not Showing	**Body Style**	Dropside L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	5

NON RUNNER-ENGINE & PARTS STRIPPED, DOES NOT POWER UP MOT SHOWS 64,759 MILES 29/11/2024

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front electric windows

Photos














NX71 VXL



FCA ITALY S.P.A.
ZFA26300006V33833
MADE IN TURKEY



Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Poor Previous Repair
Poor Paint



3: Door Mirror Assy nsf
Broken
Replace



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: B Post ns
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Lamp osr
Broken
Replace



8: B Post os
Scratched
UpTo 25mm Thru Paint



9: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No
Engine Runs	Fault		