COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**YT68LFR**

## Ford Transit Custom 280 2.0 TDCI 105PS

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Buyer To Apply |
| **Cap Id** | 42056 |
| **Cap Code** | FOTU208S0 VDTM2 1 L |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Bedford | **GVW** | 2800kg | **CAP Clean** | £5,150.00 |
| **Reg. date** | 25/09/2018 | **Colour** | WHITE | **CAP Average** | £4,400.00 |
| **Year** | 2018 | **VIN** | WF0YXXTTGYJL03268 | **CAP Below** | £3,300.00 |
| **Mileage** | 97,965 Miles Warranted | **Body Style** | Panel Van L1 | **Gearbox** | MANUAL |
| **Fuel Type** | DIESEL | **MOT Due** | 18/06/2027 | **Gears** | 6 |

*COLLECTED WITH ENGINE POWER ISSUES* SIDE LOADING DOOR

### Tyres

| | |
|---|---|
| **NSF** | |
| **NSR** | |
| **OSF** | |
| **OSR** | |
| **Spare** | |

## Features

- Park assist camera
- Front electric windows

## Photos



















FORD
e1*2007/46*1005
*WF0YXXTTGYJL03268*
CUSTOM
BASE
PANTHER 2.0 Diesel
105PS
280S
STG 6
YLF6
0,50
3CL B
GZ R
AA A
V6
2800 kg
4540 kg
1575 kg
1415 kg
W(mm)
L(mm)
a(mm)
C
2933
FCC





Speedometer
0 mph
97966.0 mls





# Condition Check




## Damage Photos



1: Wing osf
Scratched
UpTo 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips




3: Bonnet
Dented
With Paint Damage



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



11: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Chipped
Edge Chip



14: Door osf
Scratched
UpTo 25mm Not Thru Paint



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |