COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

ML20HDA

Citroen Dispatch 1000 1.5 BLUEHDI 100PS ENTERPRISE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	44718
Cap Code	CIDI15200EVDTM2 4 L

Details

Location	Bedford	**GVW**	2635kg	**CAP Clean**	£4,050.00
Reg. date	30/06/2020	**Colour**	GREY	**CAP Average**	£3,550.00
Year	2020	**VIN**	VF7VBYHRKL7031387	**CAP Below**	£2,850.00
Mileage	113,883 Miles Not Warranted	**Body Style**	Panel Van MWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	12/03/2027	**Gears**	6

D/S SIDE DOOR NEEDS ATTN, NOT CONNECTED ON ROLLERS, WARNING LIGHTS ON DASH TWIN SIDE LOADING DOORS, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Air conditioning
- Front electric windows
- Partial leather seat trim

Photos













AUTOMOBILES CITROEN
e2*2007/46*0531
VF7VBYHRKL7031387
2635 KG
4230 KG
1– 1500 KG
2– 1500 KG
VBYHRK – B2F01C
0.51









Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Screen Front
Chipped
Over 10mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Lamp nsr
Broken
Replace



9: Door nsr
Dented
With Paint Damage



10: Door osr
Dented
Between 10mm + 30mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Handle Outer osr
Broken
Replace



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



16: Door osf
Scratched
UpTo 25mm Thru Paint



17: Seat Back Cover osf
Scuffed
UpTo 25mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault