COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MF73EUZ

Iveco Daily 35-140

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	46824
Cap Code	IVDA235S44BDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Average**	£11,550.00
Reg. date	26/10/2023	**Colour**	WHITE	**CAP Below**	£9,925.00
Year	2023	**VIN**	ZCFCL35A50D741639	**Gearbox**	MANUAL
Mileage	74,653 Miles Not Warranted	**Body Style**	Dropside LWB	**Gears**	6
		CAP Clean	£12,450.00	**Tail Lift**	Column
Fuel Type	DIESEL				

WARNING LIGHTS ON DASH 3750 WB, TOW BAR, AD BLUE, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Navigation system
- Park assist camera
- Air conditioning
- Front electric windows

Photos














MF73 EUZ




IVECO
IVECO SpA
e3*2007/46*0118*
ZCFCL35A50D741639
3500 kg
7000 kg
1 - 1900 kg
2 - 2240 kg
Type IS35SI2AA
Wheelbase 3750
N° of axles 2
Engine Type F1AGL411B
Engine power kW 100
Made in SPAIN
Manufacturer name and address: IVECO S.p.A. Via Puglia 35 - 10156 Torino - ITALY
Corrected absorption value
0.507

















Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm



3: Wing osf
Scratched
UpTo 25mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Scratched
UpTo 25mm Not Thru Paint



10: Switches And Controls
Broken
Replace



11: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK