COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SE65BUV

Renault Master LL35 2.3 dCi 125PS Business

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	33476
Cap Code	R1ML23L32BLDTM2 3 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£4,775.00
Reg. date	23/12/2015	**Colour**	BLUE	**CAP Average**	£3,850.00
Year	2015	**VIN**	VF1VAE4S253981174	**CAP Below**	£2,675.00
Mileage	101,772 Miles Warranted	**Body Style**	Luton LWB	**Gearbox**	MANUAL
		MOT Due	03/02/2027	**Gears**	6
Fuel Type	DIESEL				

TWIN SIDE LOAD DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos










RENAULT
e2*2007/46*0047
VF1VAE4S253981174
3500 KG
6000 KG
1-1950 KG
2-2100 KG
RENAULT












Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Sill os
Rusted
Over 5mm



4: Qtr Panel osr
Dented
With Paint Damage



5: Tailgate
Dented
Over 30mm



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Chipped
Multiple Chips



8: Qtr Panel nsr
Dented
Over 30mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK