COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SC17RMO

Renault Master LL35 2.3 dCi 130PS Business

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38734
Cap Code	R1ML23L5T1MDTM2 3 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£7,200.00
Reg. date	22/05/2017	**Colour**	WHITE	**CAP Average**	£6,000.00
Year	2017	**VIN**	VF1VB000656524045	**CAP Below**	£4,450.00
Mileage	65,591 Miles Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	25/05/2027	**Gears**	6

TOW BAR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos









SC17 RKO

SOUTHAMPTON) LTD
*2007/46*0640*04
STAGE 2
VB000656524045




SC17 RKO






Condition Check



Damage Photos

No Image

1: Seat Base Cover osf
Torn
Over 3mm



2: Wing osf
Chipped
Multiple Chips



3: Door osf
Dented
With Paint Damage



4: Door osf
Chipped
Multiple Chips



5: Sill os
Rusted
Over 5mm



6: Door osr
Dented
With Paint Damage



7: Sill ns
Rusted
Over 5mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Wing nsf
Rusted
Over 5mm



10: Bumper Front Moulding
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK