COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SC17RMX

Renault Master LL35 2.3 dCi 145PS Business Energy

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38734
Cap Code	R1ML23L5T1MDTM2 3 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£6,400.00
Reg. date	23/05/2017	**Colour**	WHITE	**CAP Average**	£5,350.00
Year	2017	**VIN**	VF1VB000356524035	**CAP Below**	£3,950.00
Mileage	85,288 Miles Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	29/06/2027	**Gears**	6

TOW BAR, E/MIRRORS.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos

























Commercial Vehicle Auctions Limited

Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Seat Back Cover osf
Torn
Over 3mm



3: Seat Base Cover nsf
Torn
Over 3mm



4: Bonnet
Chipped
Multiple Chips



5: Door osf
Rusted
Over 5mm



6: Sill os
Rusted
Over 5mm



7: Door osf
Chipped
Multiple Chips



8: Tailgate
Rusted
Over 5mm



9: Sill ns
Dented
With Paint Damage



10: Sill ns
Rusted
Over 5mm



11: Wing nsf
Dented
With Paint Damage



12: Bumper Front
Dented
With Paint Damage



13: Bumper Front Moulding
Broken
Replace

Interior

Carpet Condition	Poor	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK