COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SC17RPY

Renault Master LL35 2.3 dCi 130PS Business

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38734
Cap Code	R1ML23L5T1MDTM2 3 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£6,575.00
Reg. date	25/05/2017	**Colour**	WHITE	**CAP Average**	£5,475.00
Year	2017	**VIN**	VF1VB000X56524047	**CAP Below**	£4,050.00
Mileage	81,475 Miles Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
		MOT Due	29/05/2027	**Gears**	6
Fuel Type	DIESEL				

WARNING LIGHTS ON DASH TOW BAR, E/MIRRORS.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos








SC17 RPY

S (SOUTHAMPTON) LTD
e11*2007/46*0640*04
STAGE 2
F1VB000X56524047








SC17 RPY





50
70
90
110
30
CHECK

Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Seat Base Cover osf
Torn
Over 3mm



3: Bonnet
Dented
With Paint Damage



4: Door osf
Dented
With Paint Damage



5: Sill os
Rusted
Over 5mm



6: Door nsf
Dented
With Paint Damage



7: Sill ns
Rusted
Over 5mm

Interior

Carpet Condition	Poor	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	Fault