COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PX19RYM

Scania R 500

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**MOT Due**	31/07/2027
Reg. date	01/06/2019	**Colour**	WHITE	**Cab Type**	HIGHLINE CAB
Year	2019	**VIN**	YS2R6X20009258065	**Gearbox**	AUTOMATIC
Mileage	1,196,412 Km Not Warranted	**Body Style**	Tractor Unit	**Axle Combi**	6x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

RETARDER, PREMIUM INFOTAINMENT SYSTEM, PREMIUM INSTRUMENTS, REAR-LIFT, SLIDING 5TH WHEEL, ALLOY WHEELS, MICROWAVE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Leather seat trim

Photos




















000km/h
1196412.7km
vehicle checks



14


SCANIA
e4*2007/46*1130
YS2R6X20009258065











SCANIA





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Panel Front
Dented
With Paint Damage



3: Panel Front
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door osf
Chipped
Multiple Chips



6: Screen Front
Cracked
Replace



7: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK