COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**HK24GXP**

## Ford Transit Custom 300 2.0 ECOBLUE 136PS LIMITED

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Buyer To Apply |
| **Cap Id** | 57334 |
| **Cap Code** | FOTU203SL1VDTA2 2 L |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Bedford | **GVW** | 3025kg | **CAP Clean** | £16,700.00 |
| **Reg. date** | 30/06/2024 | **Colour** | BLUE | **CAP Average** | £15,800.00 |
| **Year** | 2024 | **VIN** | WF0RXXTA2RRA50097 | **CAP Below** | £13,850.00 |
| **Mileage** | 68,454 Miles Not Warranted | **Body Style** | Panel Van L1 | **Gearbox** | AUTOMATIC |
| | | **MOT Due** | 29/06/2027 | **Gears** | 8 |
| **Fuel Type** | DIESEL | | | | |

*CRACKED WINDSCREEN* AD BLUE, TOW BAR, SIDE LOADING DOOR, E/MIRRORS, HEATED WINDSCREEN, ALLOY WHEELS

### Tyres

| | |
|---|---|
| **NSF** | |
| **NSR** | |
| **OSF** | |
| **OSR** | |
| **Spare** | |



## Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

## Photos





















FORD
e5*2018/858*00192
*WF0RXXTA2RRA50097*
BJFA
0.50
3025
5525
1550
1700
kg
W(mm)
L(mm)
B
3100
NRN
Ford Motor Company Limited
Aveley Road, Lilmington Essex,
RM15 6EE United Kingdom




M
R
N
D
0
mph


# Condition Check




## Damage Photos



1: Screen Front
Cracked
Replace




2: Bonnet
Chipped
Multiple Chips



3: Door nsf
Chipped
Edge Chip



4: Door nsr
Scratched
UpTo 25mm Thru Paint



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Bumper Rear
Insecure
Action Required



7: Door osf
Chipped
Edge Chip

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | OK | **Upholstery Condition** | OK |
| **Seat Condition** | OK | **Odour** | No |

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |