COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

T29SBL

Scania R 500

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	**GVW**	44000kg	**Gearbox**	AUTOMATIC
Reg. date	01/11/2018	**Colour**	WHITE	**Axle Combi**	6x2
Year	2018	**VIN**	YS2R6X20005522637	**Steering Combi**	Mid-Lift
Mileage	706,476 Km Not Warranted	**Body Style**	Tractor Unit	**Rear Suspension**	Air
Fuel Type	DIESEL	**Cab Type**	HIGHLINE CAB		

WARNING LIGHT ON DASH TWIN LINE PTO HYDRAULICS, SURROUND CAMERA SYSTEM, PREMIUM INFOTAINMENT

Tyres


NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Navigation system
- Leather seat trim
- Park assist camera
- Air conditioning
- Front electric windows

Photos













000km/h
0706477.2km
OK
1
2


T29 SBL
SCANIA
SCANIA
SCANIA


Standards Agency
Plate
Reg./Ident. Mark
T29SBL
Vehicle Identification No.
YS2R6X20005522637
Type Approval No.
Manufacturer/ Model
SCANIA /R500
Function
ARTIC R
Year of Original Registration
01/11/18
Gross Weight
23500
23500
24300
Train Weight
44000
40000
45000
44000
44000
Axle 1
7500
7500
8000
Axle 2
6000
6000
6100
Axle 3
10000
10000
10200
Axle 4
DEPARTMENT FOR
TRANSPORT
GREAT BRITAIN
REPLACEMENT


SCANIA
e4*2007/46*1130
VIN
YS2R6X20005522637
Regist. for
Total
Combination
Axle 1
Axle 2
Axle 3
Axle 4
Axle 5
(GB)
23500
44000
7500
6000
10000
Technically permissible
24300
50000
8000
6100
10200
Cab Type
Serial No.
Approval
Cab Colour
Ch.No.
Ch.Colour
ADR GTW
Ch.Type
Produced in
R 500










NO SIGNAL
BRIGADE



















Condition Check



Damage Photos



1: Wing osf
Rusted
Over 5mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Screen Front
Cracked
Replace



4: Bumper Front
Cracked
Over 25mm



5: Front TowEye Cvr
Missing
Replace



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Wing nsf
Dented
With Paint Damage



8: Door nsf
Scratched
UpTo 25mm Not Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Door osf
Chipped
Edge Chip



11: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK