COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CU67PXV

Ford Transit 350 2.0 TDCi 170ps H3

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	37875
Cap Code	FOTR203571HDTM2 4 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£3,350.00
Reg. date	01/09/2017	**VIN**	WF0XXXTTGXHA14917	**CAP Below**	£2,500.00
Year	2017	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
Mileage	109,720 Miles Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	Expired		
GVW	3500kg	**CAP Clean**	£4,025.00		

E/MIRRORS, HEATED WINDSCREEN, AD-BLUE, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

Photos












7°C
172 mls
109720mls










AIRBAG






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Roof
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Broken
Replace



4: Qtr Panel nsr
Chipped
Multiple Chips



5: Qtr Panel nsr
Dented
With Paint Damage



6: Lamp nsr
Broken
Replace



7: Qtr Panel osr
Dented
With Paint Damage



8: Qtr Panel osr
Dented
With Paint Damage




9: Door osf
Dented
With Paint Damage



10: Door Mirror Assy osf
Broken
Replace



11: Door Pad osf
Soiled
Heavy



12: Seat Base Cover osf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy



14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK