COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HT23VYH

Ford Transit Base 350 2.0 EcoBlue 130ps LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45234
Cap Code	FOTR2035331DTM2 5 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£18,550.00
Reg. date	27/07/2023	**VIN**	WF0CXXTTRCPK63299	**CAP Below**	£15,950.00
Year	2023	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Mileage	23,421 Miles Not Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	26/07/2027		
GVW	3500kg	**CAP Clean**	£20,050.00		

TOW BAR, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim

Photos











Speedometer
0 mph
23421.6 mls


UK
NI
FORD
BKRA
0.50
3500
6500
1850
2450
FED





HIGHWAY MAINTENANCE

HIGHWAY MAINTENANCE

EMERGENCY
VFS














Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace



2: Panel Front
Scratched
Over 25mm Not Thru Paint



3: Panel Front
Scratched
Over 25mm Not Thru Paint



4: Door nsf
Dented
With Paint Damage



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Fuel Flap
Cracked
Replace



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door osr
Scratched
Over 25mm Thru Paint



10: Seat Base Cover osr
Soiled
Heavy



11: Seat Base Cover nsr
Soiled
Heavy



12: Seat Back Cover osr
Soiled
Heavy



13: Seat Back Cover nsf
Soiled
Heavy



14: Seat Back Cover osf
Soiled
Heavy



15: Seat Base Cover nsf
Soiled
Heavy



16: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK