COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DX20UKT

Daf XF 450

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Avonmouth	**GVW**	44000kg	**Cab Type**	SPACE CAB
Reg. date	01/03/2020	**Colour**	BLACK	**Gearbox**	AUTOMATIC
Year	2020	**VIN**	XLRTGH4100G303293	**Axle Combi**	6x2
Mileage	468,289 Km Not Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Fuel Type	DIESEL	**MOT Due**	Expired	**Rear Suspension**	Air

WARNING LIGHTS ON DASH

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim

Photos












0km/h
468290.7km
Scan me!
OK


DX20 UKT
DAF
DAF


Plating Certificate
DX20UKT
XLRTGH4100G303293
DAF /XF 450 FTP
ARTIC R
01/03/20
2020
REPLACEMENT


DAF TRUCKS N.V.
XLRTGH4100G303293
23900 kg
44000 kg
1 - 8000 kg
2 - 4400 kg
3 - 11500 kg
4 - kg
T - 15900 kg
Type
Motor




















R
N
D


DAF
















Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Panel Front
Chipped
Over 5mm



3: Wing nsf
Cracked
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



10: Wheel nsf
Corroded
Light



11: Door nsf
Chipped
Edge Chip



12: Qtr Panel nsr
Chipped
Over 5mm



13: Wheel nsr
Corroded
Light



14: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



16: Wheel osr
Corroded
Light



17: Qtr Panel osr
Chipped
Over 5mm



18: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



19: Wheel osf
Corroded
Light



20: Door osf
Chipped
Edge Chip



21: Door osf
Chipped
Over 5mm



22: Wing Front Arch Extension os
Broken
Replace



23: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



24: Wing osf
Cracked
Replace



25: Bumper Front
Chipped
Over 5mm



26: Bumper Front
Chipped
Over 5mm



27: Grille Front
Broken
Replace



28: Seat Base Cover osf
Torn
Over 3mm



29: Switches And Controls
Missing
Replace



30: Seat Base Cover nsf
Torn
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited