COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ22OBU

Ford Transit 300 2.0 EcoBlue 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	42069
Cap Code	FOTU203SL0VDTM2 1 L

Details

Location	Avonmouth	**GVW**	3000kg	**CAP Clean**	£13,150.00
Reg. date	22/04/2022	**Colour**	BLUE	**CAP Average**	£11,950.00
Year	2022	**VIN**	WF0YXXTTGYNL87887	**CAP Below**	£10,050.00
Mileage	47,279 Miles Not Warranted	**Body Style**	Panel Van L1	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	04/12/2026	**Gears**	6

AD BLUE, SIDE LOAD DOOR, ROOF RACK, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN


Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Digital radio
- Drivers airbag
- Heated front seat
- USB/iPod interface
- Passenger airbag

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Grille Front
Scratched (Painted)
Over 25mm Thru Paint



3: Fog Lamp Surround ns
Broken
Replace



4: Bumper Front Moulding
Broken
Replace




5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear Moulding
Broken
Replace



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door nsr
Dented
With Paint Damage



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door nsr
Scratched
Over 25mm Thru Paint



19: Door osr
Scratched
Over 25mm Thru Paint



20: Bumper Rear
Scratched
25 to 100mm Thru Paint



21: Qtr Panel osr
Chipped
Multiple Chips



22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel Moulding ns
Scratched (Painted)
UpTo 25mm Thru Paint



24: Door osf
Chipped
Multiple Chips



25: Door osf
Scratched
Over 25mm Thru Paint



26: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



27: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		